

TCM Technik Project Level	LEVEL 1	Optimization of individual processing	Existing part / new part	Individual (special) tool	
	LEVEL 2	RE- Tooling	Existing part	Several or all tools	
	LEVEL 3	Creation of a CPU offer with tool cost list (Tool costs / part)	New part / existing part (recalculation)	All tools	
	LEVEL 4	Complete processing of the machining strategies by the customer	New part	All tools	
	LEVEL 5	Complete processing of the machining strategies by TCM	New part	All tools	
	LEVEL 6	Complete project machining strategies by TCM (evtl. with AEC)	New part	All tools	Incl. fixture and CNC program